



[Support Center](#) > [Community](#) > [Debugging](#) > [debugger connect fail](#)

debugger connect fail **Awaiting Agent**

- ph peng han
- **Forum name:** #Debugging

hello

The problem I encountered was that the debugger connection failed. The reason for the failure was that the debug port fail.

The chip I'm using is RW610. Why isn't the RW610 chip listed in the chip selection?

Why did the chip fail to establish a connection when choosing Cortex-m33?

Comment (1)

Ahmed Regaieg

5 months ago

This CPU selection has been public since 06/03/2025. To use it, you need a TRACE32 software version newer than the latest public release R.2025.02. I will send you a more recent software update by private email.

Please note that some cores require specific initialization settings before communication can be established. This is why it is important to select the correct CPU name.