



[Support Center](#) > [Community](#) > [Board Bring-Up](#) > [\[RH850U2A CSI\] Serial Flash Programming failed](#)

## **[RH850U2A CSI] Serial Flash Programming failed** **Awaiting Agent**

- D DungNguyen
- **Forum name:** #Board Bring-Up

Dear lauterbach experts,

Currently I'm trying to use the TRACE32 to update the option bytes of RH850U2A according to rh850\_serialflashprog.cmm demo (with debug port type CSI). But SYStem.Mode Prepare always report the error "debug port failed" so I could not do anything else.

For debug port type LPD4, I can run SYStem.Mode Up successfully and flash SW.

Please help me review if anything needs to be prepared to run Serial Flashing Mode.

Thank you so much!