



Knowledgebase > TRACE32 PowerView > [Simulink] TRACE32 XIL: Cannot find header file for TRACE32 Remote API

[Simulink] TRACE32 XIL: Cannot find header file for TRACE32 Remote API

2023-10-25 - Comments (0) - TRACE32 PowerView

This error is returned in case the C/C++ MEX compiler has not been configured in MATLAB after installing a supported compiler. Please refer to the following links for more information:

<https://www.mathworks.com/support/requirements/supported-compilers.html>

https://www.mathworks.com/help/matlab/matlab_external/changing-default-compiler.html

This error is also displayed in the following cases:

- The TRACE32 integration with Simulink cannot find the t32api library in the TRACE32 installation under demo/api/capi/dll (t32api64.dll / t32api.dll for Windows or t32api64.so for Linux)
- The TRACE32 integration with Simulink cannot find the header file t32.h in the TRACE32 installation under demo/api/capi/src