Infineon TC297 chip, SCU_RSTSTAT CB1 and CB3 reset after product mode decryption. Open Discussion

- L LIANZE
- **Forum name:** #Debugging

Hello Lauterbach debugging experts, I am using the TC297 chip. The current development mode samples have no reset, but the product mode samples are decrypted to show a reset of CB1 and CB3. This reset appears to be initiated by the debugger. How do I find the root cause of this problem?
Thanks!

Comment (1)

Amira Tmar
1 year ago
Thank you for reaching out. To help us investigate the issue further, we'll need some additional details about your setup. Please submit a new ticket using your corporate email address via the following link: https://support.lauterbach.com/new-ticket We appreciate your cooperation and look forward to assisting you.