What is the recommended way to use the debug cable to avoid any defect?

2023-10-24 - Comments (0) - Setup / update

It is always recommended to "only" connect and disconnect debugger to/from the target when the target is powered OFF.

So, the recommended sequence is:

1- both debugger and target powered off

2- power on debugger

3- start TRACE32

4- connect debugger to target

5- power on target