Best practices for folders and path of TRACE32 environment Open Discussion

- AM Aurelien Morfouace
- **Forum name:** #Other Use Cases

Does someone has good best practices or recommandation how to organize the TRACE32 debug environment in which we can have a batch file to start the TRACE32 with some other scripts?

Comment (1)

Wiem Wala Benayed
2 months ago
You can call this command inside the batch script (the -e option for connection script and -s option for startup script): \t32marm.exe -e connection_setup.cmm -s startup_debug.cmm More details in ide_user.pdf under "Interactive Connection Mode" and "Connection Script Generation for Test Automation" and installation.pdf under “Command Line Arguments for Starting TRACE32”