LAUTERBACH

j784s4-cr5-mcu_ddr.cmm hang on TI J784S4 EVM board Awaiting Agent

- Jim Zhang
- **Forum name:** #Debugging

The DDR PLL configuration cause board spinning forever

Comment (1)

Ahmed Ghribi
5 months ago
Hello Jim, This is part of our script based board setup demo, it expects a General Purpose target and the boot mode is set to "No Boot". I have sent a private email for further details. Best regards,Ahmed Ghribi