[AUTOSAR] Trace.Chart.TASK only displays "(unknown)". ORTI and ELF files are loaded.

2026-07-31 - Comments (0) - OS-aware debugging

Most probably the trace is missing the task switches. You can enable tracing the task switches with the command

```
Break.Set task.config(magic) /Write /TraceData
```

This enables a data trace on the variable that holds the current running task. This is extracted from the ORTI file ("RUNNINGTASK").

- Tags
- AUROSAR
- ORTI
- OSEK
- RUNNINGTASK