How can I save the contents of a TRACE32 window to a file?

2026-07-31 - Comments (0) - PRACTICE

Use the `PRinTer.FILE` command to specify the output file and the `WinPrint` command to write the contents of a TRACE32 window to that file.

By default, `PRinTer.FILE` overwrites the output file if it already exists. To append the output to an existing file instead, use the `/Append` option.

Examples

Append the contents of the **Trace.List** window to a text file:

```
PRinTer.FILE output.txt /Append
WinPrint.Trace.List
```

Print a memory range from the **Data.dump** window:

```
WinPrint.Data.dump 0x0--0xFFF
```

Generate an XHTML file containing a section of the **List.Mix** window:

```
PRinTer.FILE file01.html XHTML
WinPrint.List.Mix func7--func17
```

For a complete description of the supported output formats and `WinPrint` variants, refer to the PowerView Command Reference.