How can I program a temporary software warranty license?

2025-04-02 - Comments (0) - Setup / update

We offer our customers a one-time temporary software warranty license key to test a new software version for four weeks. This requires a registered serial number.

To activate the license, start a TRACE32 PowerView instance connected to your debug probe then run the following command:

LICENSE.UPDATE <Debug_Probe_Serial_Number> <Expiration_Date> <License_Key_Code>

- <Debug_Probe_Serial_Number>: The serial number of your debug probe.

- <Expiration_Date>: The end date of the temporary license period.

- <License_Key_Code>: The provided license key.

Alternatively, you can activate the license using the **LICENSE.state** window. Run LICENSE.state in the TRACE32 command line, then copy the expiration date into the **"valid up to version"** field and the maintenance code into the **"code"** field. Finally, press **"Save key to file"** to store the license.

The license will be stored in the license.t32 file within your TRACE32 system directory (e.g., C:\T32). It is **not** stored on the debug probe itself.

For more information about the LICENSE.UPDATE command, refer to the PowerView Command Reference.