



<u>Support Center</u> > <u>Community</u> > <u>Debugging</u> > <u>How to show multiple Y axis in profile window?</u>

How to show multiple Y axis in profile window? Awaiting Agent

• H Hudson

• Forum name: #Debugging

When watching multiple variables in Trace32 profile window, how to show Y axis for each variables respectively?

Comments (3)

Wiem Wala Benayed

9 months ago

Do you want that each variable has its own Y axis but within the same Var.PROfile window? This is not possible.

Otherwise, can you clarify your request?

$H \; \textbf{Hudson}$

8 months ago

Oh, sad. yes, I just want each variable has its own Y axis. Because the data range is different. When I show the variables in different profile window, I found that the windows can't be tracked, means the time axis is not synchronized. If they are in same profile window and with different axis, then there is no this issue. see figure attached.

H Hudson

8 months ago

sorry, in the comment window, attachment can't be added.