



Knowledgebase > PRACTICE > How can I print the content of a TRACE32 window into a file?

How can I print the content of a TRACE32 window into a file?

2021-09-17 - Comments (0) - PRACTICE

The commands **PRinTer.FILE** and **WinPrint** can be used to print a TRACE32 window into a file.

The **/Append** option of the **PRinTer.FILE** command can be used to append new data to the existing file. Without **/Append**, file contents are overwritten if the file already exists.

Examples:

PRinTer.FILE output.txt /Append

WinPrint.Trace.List

WinPrint.Data.dump 0--0xff

PRinTer.FILE file01.html XHTML

WinPrint.List.Mix func7--func17

Please refer for more information to the [PowerView Command Reference](#).