



Knowledgebase > FAQs by core architecture > RH850 > [RH850] Toggling Data Flash values

[RH850] Toggling Data Flash values

2022-01-11 - Comments (0) - RH850

For RH850, "toggling values" is the normal behavior for not-programmed Data-Flash. Reading these addresses will return undefined results. This is also described in the CPU User-Manual.