

Knowledgebase > Setup / update > What is the recommended way to use the debug probe to avoid any defect?

What is the recommended way to use the debug probe to avoid any defect?

2025-10-09 - Comments (0) - Setup / update

It is always recommended to "only" connect and disconnect debugger to/from the target when the target is powered OFF.

So, the recommended sequence is:

- 1- both debugger and target powered off
- 2- power on debugger
- 3- start TRACE32
- 4- connect debugger to target
- 5- power on target