



[Support Center](#) > [Community](#) > [Other Use Cases](#) > [Best practices for folders and path of TRACE32 environment](#)

Best practices for folders and path of TRACE32 environment

Awaiting Agent

- AM Aurelien Morfouace
- **Forum name:** #Other Use Cases

Does someone has good best practices or recommandation how to organize the TRACE32 debug environment in which we can have a batch file to start the TRACE32 with some other scripts?

Comment (1)

Wiem Wala Benayed

1 day ago

You can call this command inside the batch script (the -e option for connection script and -s option for startup script): `\\t32marm.exe -e connection_setup.cmm -s startup_debug.cmm` More details in `ide_user.pdf` under "Interactive Connection Mode" and "Connection Script Generation for Test Automation" and `installation.pdf` under "Command Line Arguments for Starting TRACE32"