

## How can I realize a silent installation under Windows?

2024-01-12 - Comments (0) - Setup / update

1. For a simple software roll out of a company unique TRACE32 software installation, a network mount/drive will be used and the content of the TRACE32 DVD should be in a special directory on a server

**xcopy D:\\*.\* N:\TRACE32DVD\_201011 /E /V /L      // drive and  
directory name are only an example**

2. Record once a TRACE32 installation with the following instructions inside a command shell window:

**N:  
cd N:\TRACE32DVD\_202109\files\bin\setup64      // drive name N:  
and the directory is only an example**

**// and must be replaced by the actual user-defined values**

**setup.exe /r /f1"N:\TRACE32DVD\_201011\bin\setup64\setup.iss"**

**// /r stands for enabling recording the installation process**

**// /f1 defines the file which will contain the recorded installation  
actions**

Step through the complete TRACE32 installation process, the record will be saved in the setup.iss file.

3. Start a silence TRACE32 installation with the following instruction on a different PC:

**setup.exe /s /f1"N:\TRACE32DVD\_201011\bin\setup64\setup.iss"    // /s  
means silence installation mode**

If InstallShield didn't work correctly with a record file on the network drive, please use the following default place C:\rul\setup.iss instead.