



[Knowledgebase](#) > [Setup / update](#) > [No debug cable plugged, demo limited to 5 minutes](#)

## No debug cable plugged, demo limited to 5 minutes

2026-05-15 - [Comments \(0\)](#) - [Setup / update](#)

The error message “**No debug cable plugged, demo limited to 5 minutes**” indicates that TRACE32 PowerView is unable to detect the debug probe (debug cable). Please verify that the debug probe is properly connected to the debug module.

The issue may also be caused by a defective debug probe. If possible, perform a cross-check using a different debug probe to determine whether the original probe is faulty.