



Knowledgebase > TRACE32 PowerView > Suffixes as .isra, .constprop. or .part added to symbols

Suffixes as .isra, .constprop. or .part added to symbols

2022-01-10 - Comments (0) - TRACE32 PowerView

This is due to Link Time Optimization LTO which appends strings like .isra, .constprop. or .part..

You may try to disable LTO. Otherwise, you can use the command **sYmbol.ForEach** to find all symbols with a special suffix. Refer to [General Commands Reference Guide S](#) for more information about the **sYmbol.ForEach** command.

Tags

sYmbol